

Hygiene-Institut des Ruhrgebiets


Institut für Umwelthygiene und Toxikologie

Director: Dr. Thomas-Benjamin Seiler

Legal Entity: Verein des Hygiene-Instituts des Ruhrgebiets e.V.

Hygiene-Institut · PO Box 10 12 55 · DE 45812 Gelsenkirchen · Germany

HEATEX AB
Hyllie Boulevard 34
215 32 Malmö
Sweden



Address:
Rotthäuser Str. 21, DE 45879 Gelsenkirchen

Switchboard +49 (0)209 9242-0
Internet www.hyg.de

Our reference: W-420649e-26-Zd
Contact person: B. Zeidler

Gelsenkirchen, 21.10.2026

Test - certificate

hygiene-conformity check to the design requirements of
selected regulations

Test institute: Hygiene Institut des Ruhrgebiets
Institut für Umwelthygiene und Toxikologie
Rotthäuser Straße 21
45879 Gelsenkirchen

Test object: Rotary heat exchangers of the types
EA, OA, EQA, EVA, ENA, ESA, ERA
EE, OE, EQE, EVE, ENE, ESE, ERE
EL, OL, EQL, EVL, ENL, ESL, ERL
EM, OM, EQM, EVM, ENM, ESM, ERM

Manufacturer: HEATEX AB
Hyllie Boulevard 34
215 32 Malmö
Sweden



Basis of the examination: ✓ VDI 6022, sheet 1 (01/2018)* ✓ VDI 3803, sheet 1 (05/2020)
 ✓ ÖNORM H 6020 (03/2024)** ✓ ÖNORM H 6021 (01/2023)
 ✓ SWKI VA104-01 (01/2019)* ✓ SWKI VA105-01 (08/2015)*

Validity period: 5 years 10/2026 – 10/2031

Test report: W-420650-26-Zd, W-420651-26-Zd, W-420652-26-Zd, W-420653-26-Zd

In conclusion it can be stated that the examined Rotary heat exchangers, as specified in the test reports W-420650-26-Zd, W-420651-26-Zd, W-420652-26-Zd and W-420653-26-Zd, is in compliance with the above mentioned regulations.



(B. Zeidler)

clerk of the Department hygienic building technology



(J. Rolle B.Eng.)

clerk of the Department hygienic building technology

issued 21.10.2026, Gelsenkirchen

* The use of rotary heat exchangers is not possible in rooms in which no inter-room recirculation mode is permitted (see also DIN EN 16798-3) and where there are increased hygienic requirements. Heat recovery units with leaks are always to be regarded as circulating air if a sufficient, controlled pressure gradient from the outside air to the exhaust air is not ensured in the heat recovery. Pollutant transfer through co-rotation is also to be assessed. If such a transfer cannot be ruled out, these heat recovery systems may only be used if the use of circulating air in the system is also hygienic.

** - Cannot be used in areas in which the exhaust air contains radioactive substances or in systems for infection departments, prosecutes and animal experimental departments, the hygienic suitability of the device for the specific purpose must also be proven by an expert opinion

Within the framework of the conformity check the hygiene-relevant requirements of the above mentioned regulations was examined. Requirements of other regulations that refer to the above mentioned regulations were not part of the examination. Additionally, the conformity check does not include a toxicological or sensory testing of the introduced materials.